

LX5200 Skidsteer Log Grapple Parts Manual

Starting with S/N 6520061 & After



Foreword

EMB Mfg. has prepared this parts manual to assist customers in ordering quality OEM replacement parts.

Proper and regular service and replacing old, worn or broken parts with the correct OEM parts are essential to prolonging the life of your EMB product. Please refer to this manual before ordering any replacement parts.

All information contained in this parts manual is based on the latest product specification available at the time of printing this manual. If your product differs from the specifications contained within this manual contact EMB Mfg. for information.


EMB reserves the right to alter specifications on their products at any time.

Reproduction of this parts manual of any kind is prohibited without prior written permission from EMB Mfg.


Table of Contents

Main Parts	5
Grapple	6
Cylinder	7
Decal Breakdown	8






Aug 2015 Page 5



Page 6 Aug 2015





ITEM	6012C205	Description	QTY.
1	6012C2053	Rod	1
2	6012C2054	Barrel, 2" / 2-1/2"Bore	1
3	G250-150S	Rod Gland	1
4	P100-250SP	2" / 2-1/2" Bore Piston	1
5	SLK-2515	Seal Kit	1
6	Z72272G8	Hex Lock Nut 3/4NF Grade 8	1

Aug 2015 Page 7

LOG GRAPPLE DECAL BREAKDOWN

ITEM	PART NO.	DESCRIPTION	QTY
1	Z94155	LX5200 LH	1
2	Z94156	LX5200 RH	1
3	Z94019	Made in Canada	1
4	Z94033	Boom/ Grapple Hazard	1
5	emb-079	Read Manual	1





Page 8 Aug 2015

LX5200 Decals





Z94019



Z94033



emb-079





- engine, remove ignition key and wait for all moving parts to stop before servicing, adjusting, repairing o maintaining.
- Do not allow bystanders within 20 feet (6 m) of machine to prevent injury from rolling logs.
- Wear appropriate safety gear including but not limited to a hard hat, safety glasses, hearing protection, safety shoes and heavy gloves.
- Operate only on level ground.
- Do not operate on hillside or when working area is cluttered, wet, muddy or icy to prevent slipping or tripping.
- Do not allow riders.
- Keep all hydraulic components in good repair.

Aug 2015 Page 9

TWO PANEL LOG GRAPPLE DECAL BREAKDOWN

ITEM	PART NO.	DESCRIPTION	QTY
1	Z94155	LX5200 LH	1
2	Z94156	LX5200 RH	1
3	Z94019	Made in Canada	1
4	Z94033	Boom/ Grapple Hazard	1
5	emb-079	Read Manual	1





Page 10 Aug 2015

Two Panel LX5200 Decals









Z94119



Z94166





WALLENSTEIN Products Manufactured by:

EMB MFG Inc.

4144 Boomer Line St. Clements, Ontario Canada NOB 2M0 Phone: 1-877-695-9283

Fax: 519-699-4146 www.embmfg.com